



Karnataka Fire and Emergency Services Department

Office of the District fire officer,

Tumkur Fire station

BH Road, Tumkur – 572 103.

Ph No.0816 – 2283101.



No.05/CC/DFO/TFS/2025.

Date:24-01-2025.

To,
The Authorized Signatory
M/s. CIT Public School,
Herur-Gubbi,
Tumkur District.

Sir,

Sub: Renewal of “**Compliance report**” with respect to fire prevention, fire fighting and evacuation measures Provided & maintained at **M/s. CIT Public School, Herur-Gubbi, Tumkur District.**

Ref: 1. Fire Safety Recommendation No.612/FSR/CFO/BWZ/2020.date:18-01-2021.
2. Compliance Report No.04/CC/DFO/TMK/2024.date:04-01-2024.
3. Your letter dated 20/01/2025.

*** **

With reference to subject above cited, a ‘Fire Safety Recommendation’ was issued wide reference (1) to the premises of **M/s. CIT Public School, Herur-Gubbi, Tumkur District.** with a condition to fulfill the recommendations and compliance the same within 3 months.

As per reference cited (2) above Fire Safety Compliance Certificate was issued for above school premises.

With reference cited (3) above, the applicant has requested to this office for renewal **Compliance Certificate**, In this regard I have re-inspected the premises of **M/s. CIT Public School, Herur-Gubbi, Tumkur District.** on **22/01/2025** for Renewal of Compliance Certificate. the management of School was complied the all recommendation communicated in Fire Safety Recommendation.

Under the above circumstances the Karnataka Fire & Emergency Services Department is issuing the ‘**Renewal Fire Safety Compliance Certificate**’ to **M/s. CIT Public School, Herur-Gubbi, Tumkur District.** subject to proper maintenance of fire fighting systems


This Fire Safety Compliance Certificate was issued for only Two years from the date of issue and it is renewable.


DIRECTOR

C.I.T. GROUP OF INSTITUTIONS
GUBBI, TUMKUR -572216.


PRINCIPAL

CIT PUBLIC SCHOOL
CBSE Aff. No. 831205
HERURU, B.H. Road, Gubbi Ta.

Yours faithfully,

District Fire Officer 24/01/25
Karnataka Fire & Emergency Service
Tumakuru-572 103